

Product name	Confidentiality level
B310s-22	CONFIDENTIAL
Product version	Total 12 pages
V1.0	

# B310s-22 21.323.03.01.11

## Firmware Release Notes

Prepared by	B310s-22 Team	Date	2017-06-06
Reviewed by	B310s-22 Team	Date	2017-06-06
Approved by	B310s-22 Team	Date	2017-06-06



Huawei Technologies Co., Ltd.

All rights reserved

## Revision Record

<b>Date</b>	<b>Revision version</b>	<b>FW-WebUI/HiLink Version</b>	<b>Change Description</b>	<b>Author</b>
2017-06-06	1.0	21.323.03.00.11	Mainline Version	B310s-22 Team
2017-06-07	1.0	21.323.03.01.11	Mainline Version	B310s-22 Team

# Table of Contents

1	Main Features .....	4
2	Hardware.....	4
2.1	Version Description .....	4
2.2	Hardware Specifications .....	5
2.3	Improvements in the Previous Version .....	6
2.4	Known Limitations and Issues .....	6
3	Firmware .....	6
3.1	Version Description .....	6
3.2	Firmware Specifications .....	6
3.3	Improvement in the Previous Version .....	7
3.4	Known Limitations and Issues .....	7
4	WebUI.....	7
4.1	Version Description .....	7
4.2	WebUI/HiLink Specifications .....	7
4.3	Improvement in the Previous Version .....	7
4.4	Known Limitations and Issues .....	7
5	Software Vulnerabilities Fixes .....	8



# B310s-22 Firmware Release Notes

Abbreviations	description

## 1 Main Features

The B310s-22 mainly supports the following features:

- LTE FDD (DL) data service of up to 150 Mbps
- LTE FDD (UL) data service of up to 50 Mbps
- LTE TDD (DL) data service of up to 112 Mbps
- LTE TDD (UL) data service of up to 10 Mbps
- DC-HSPA+ (DL) data service of up to 42 Mbps
- HSPA+ (DL) data service of up to 21.6 Mbps
- HSDPA (DL) data service of up to 14.4 Mbps
- HSUPA (UL) data service of up to 5.76 Mbps
- UMTS data service of up to 384 kbps
- EDGE data service of up to 236.8 kbps
- EDGE data service of download to 296 kbps
- GPRS data service of up to 85.6 kbps
- CS voice
- Online software upgrade
- LED indicators
- Windows XP SP3, Windows Vista SP1/SP2, Windows 7, Windows 8, Windows 8.1 (does not support Windows RT), MAC OS X 10.7, 10.8 and 10.9 with latest upgrades

## 2 Hardware

### 2.1 Version Description

Hardware Version:	WL1B310FM03 (B310s-22)
Platform & Chipset:	Balong Hi6921 & AR 8035



## 2.2 Hardware Specifications

Item	Specifications	
Technical standard	WAN: LTE/ DC-HSPA+/HSPA+/HSPA/UMTS/EDGE/GPRS/GSM	
Operating frequency	LTE: B1/B3/B7/B8/B20/B38	
	HSPA+/HSPA/UMTS: B1/B8	
	EDGE/GPRS/GSM: 1900/1800/900/850 MHz	
Internal memory	512 MB Flash,256 MB Memory	
Maximum transmitter power	UMTS: 24 (+1/-3) dBm	
Receiver sensitivity	UMTS: Confirm to 3GPP Requirements	
Maximum power consumption	12 W	
Power supply	AC: 100–240 V	
	DC: 12 V, 1 A	
External interfaces	LAN: 1 RJ45,GE FXS:1 RJ11	
	SIM card interface: standard 6-pin SIM card interface	
Indicators	Mode:	cyan: 4G mode blue: 3G mode yellow: 2G mode green: WAN mode Red: No SIM/USIM card is found, the PIN is not verified, or the SIM/USIM card is not working properly. Failed to connect to a mobile network
	Signal	One to three: Weak to Strong signal Off: out signal
	WPS/WIFI	Off
	Voicemail Indicators	On/Off
	Power	On/Off
Dimensions (D x W x H)	180 mm x126 mm x38mm	
Weight	about 226 g (Does not contain the power adapter)	



Item	Specifications
Temperature	Operating: 0°C to +40°C
	Storage: -20°C to +70°C
Humidity	5% to 95% ( non-condensing)

### 2.3 Improvements in the Previous Version

Index	Case ID	Issue Description
NA		

### 2.4 Known Limitations and Issues

Index	Case ID	Issue Description
NA		

## 3 Firmware

### 3.1 Version Description

Firmware Version: 21.323.03.01.11  
 Baseline information BalongV700R110C30B321  
 OS VxWorks 6.8+linux 3.4.5

### 3.2 Firmware Specifications

Item	Description
Voice	<ul style="list-style-type: none"> <li>Support CS voice</li> </ul>
SIM lock	<ul style="list-style-type: none"> <li>Without SIM lock</li> </ul>
Web UI	<ul style="list-style-type: none"> <li>Only support local update for web UI</li> </ul>
Online update	<ul style="list-style-type: none"> <li>Support Force online update</li> </ul>
VoLTE	<ul style="list-style-type: none"> <li>Not Support</li> </ul>
VoIP	<ul style="list-style-type: none"> <li>Not Support VoIP</li> </ul>
TR069	<ul style="list-style-type: none"> <li>Not Support TR069</li> </ul>
PIN	<ul style="list-style-type: none"> <li>Support unlock PIN via fixed phone</li> </ul>
PUK	<ul style="list-style-type: none"> <li>Not support unlock PUK.</li> </ul>



### 3.3 Improvement in the Previous Version

Index	Issue Description
1	<i>Fixed the bug: voicemail LED Indicator will slake when incoming call no answer.</i>

### 3.4 Known Limitations and Issues

Index	Case ID	Issue Description

## 4 WebUI

### 4.1 Version Description

WebUI Version: 17.100.09.00.03

### 4.2 WebUI/HiLink Specifications

Item	Specifications

### 4.3 Improvement in the Previous Version

Index	Case ID	Issue Description

### 4.4 Known Limitations and Issues

Index	Case ID	Issue Description



## 5 Software Vulnerabilities Fixes

Software/Module name	Version	CVE ID	Vulnerability Description	Solution
Portable UPnP SDK	LibUPnP 1.6.12	CVE-2012-5960	resolved	Refer:DTS2013012408852
Portable UPnP SDK	LibUPnP 1.6.12	CVE-2012-5959	resolved	Refer:DTS2013012408852
Portable UPnP SDK	LibUPnP 1.6.12	CVE-2012-5958	resolved	Refer:DTS2013012408852
Samba	3.0.37	CVE-2013-4475	Don't involve closing	Refer to the Samba website corresponding vulnerability, the problems in the Samba3.2.0 version, the current version is 3.0.37, refer : <a href="http://www.samba.org/samba/security/CVE-2013-4475">http://www.samba.org/samba/security/CVE-2013-4475</a>
Samba	3.0.37	CVE-2013-4124	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2013-0454	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2013-0214	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2013-0213	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2012-1182	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2011-2724	Don't involve closing	Refer:DTS2013101600954
Samba	3.0.37	CVE-2011-2694	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2011-2522	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2011-1678	Don't involve closing	Refer:DTS2013101600954,/etc is a read-only file cannot be tampered with
Samba	3.0.37	CVE-2011-0719	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2010-3069	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2010-2063	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2010-1642	resolved	Refer:DTS2013101600954
Samba	3.0.37	CVE-2010-1635	Don't involve closing	Refer:DTS2013101600954,there is no problem of output has been done to determine
Samba	3.0.37	CVE-2010-1635	Don't involve	Refer:DTS2013101600954,fu



		0-0547	closing	nction problems do not exist without treatment
Samba	3.0.37	CVE-2012-6150	Don't involve closing	Refer to the Samba website corresponding vulnerability to explain the problem, in the 3.3.10, 3.4.3, 3.5.0 and later  Later, the current version is 3.0.37, the specific reference : <a href="http://www.samba.org/samba/security/CVE-2012-6150">http://www.samba.org/samba/security/CVE-2012-6150</a>
Samba	3.0.37	CVE-2013-4408	Don't involve closing	Refer:DTS2014011403455, the current version does not have this function, do not need to deal with
Openssl	0.98y	CVE-2014-3470	resolved	Refer:DTS2014060606113
Openssl	1.0.0a	CVE-2014-3470	resolved	Refer:DTS2014060606113
Openssl	1.0.1e	CVE-2014-3470	resolved	Refer:DTS2014060606113
Openssl	0.98y	CVE-2014-0224	resolved	Refer:DTS2014060606113
Openssl	1.0.0a	CVE-2014-0224	resolved	Refer:DTS2014060606113
Openssl	1.0.1e	CVE-2014-0224	resolved	Refer:DTS2014060606113
Openssl	0.98y	CVE-2014-0221	resolved	Refer:DTS2014060606113
Openssl	1.0.0a	CVE-2014-0221	resolved	Refer:DTS2014060606113
Openssl	1.0.1e	CVE-2014-0221	resolved	Refer:DTS2014060606113
Openssl	0.98y	CVE-2014-0198	resolved	Refer:DTS2014060606113
Openssl	1.0.0a	CVE-2014-0198	resolved	Refer:DTS2014060606113
Openssl	1.0.1e	CVE-2014-0198	resolved	Refer:DTS2014060606113
Openssl	0.98y	CVE-2014-0195	resolved	Refer:DTS2014060606113
Openssl	1.0.0a	CVE-2014-0195	resolved	Refer:DTS2014060606113
Openssl	1.0.1e	CVE-2014-0195	resolved	Refer:DTS2014060606113
Openssl	0.98y	CVE-2014-0076	resolved	Refer:DTS2014042811358
Openssl	0.98y	CVE-2014-3512	resolved	Refer:DTS2014082103995
Openssl	0.98y	CVE-2013-6450	resolved	Refer:DTS2014020804489
Samba	3.0.37	CVE-2013-4496	Don't involve closing	CVE-2013-4496 vulnerability exists in the 3.4.0 version, the version is 3.0.37, without the need to merge.





		4-3513		
Openssl	1.0.1e	CVE-2014-3566	resolved	Refer:DTS2014101702663
Openssl	1.0.1e	CVE-2014-3567	resolved	Refer:DTS2014101702663
Openssl	1.0.1e	CVE-2014-3568	resolved	Refer:DTS2014101702663
Openssl	1.0.1a	CVE-2014-3513	resolved	Refer:DTS2014101702663
Openssl	1.0.1a	CVE-2014-3566	resolved	Refer:DTS2014101702663
Openssl	1.0.1a	CVE-2014-3567	resolved	Refer:DTS2014101702663
Openssl	1.0.1a	CVE-2014-3568	resolved	Refer:DTS2014101702663
		CVE-2014-3568	resolved	Refer:DTS2014101702663
		CVE-2014-3567	resolved	Refer:DTS2014101702663
		CVE-2014-3566	resolved	Refer:DTS2014101702663
		CVE-2014-3513	resolved	Refer:DTS2014101702663
		CVE-2014-2851	resolved	Refer:DTS2015021307041
		CVE-2013-1763	resolved	Refer:DTS2015021307041
		CVE-2014-4943	resolved	Refer:DTS2015021307041
Samba	3.0.37	CVE-2015-5252	resolved	Refer: DTS2016011910731
linux kernel	3.4.5	CVE-2015-1805	resolved	Refer: DTS2016032907086
Android	4.4_r1	CVE-2016-0774	resolved	Refer: DTS2016042909004
		CVE-2016-2438	resolved	Refer: DTS2016042909004
Openssl	1.0.1a	CVE-2016-2105	resolved	Refer: DTS2016051206645
		CVE-2016-2106	resolved	Refer: DTS2016051206645
		CVE-2016-2107	resolved	Refer: DTS2016051206645
		CVE-2016-2108	resolved	Refer: DTS2016051206645
		CVE-2016-2109	resolved	Refer: DTS2016051206645
		CVE-2016-2176	resolved	Refer: DTS2016051206645
Wifi		CVE-2016-0801	resolved	Refer: DTS2016031502450
		CVE-2016-0802	resolved	Refer: DTS2016031502450
Openssl		CVE-2015-8816	resolved	Refer: DTS2016082503595
		CVE-201	resolved	Refer: DTS2016082503595



		6-0723		
		CVE-2016-3757	resolved	Refer: DTS2016082503595
		CVE-2016-2842	resolved	Refer: DTS2016071304872
		CVE-2015-2686	resolved	Refer: DTS2016071304872
		CVE-2016-3841	resolved	Refer: DTS2016071304872
		CVE-2016-4482	resolved	Refer: DTS2016071304872
Iptables		CVE-2014-9529	resolved	Refer: DTS2016080404468
		CVE-2015-5364	resolved	Refer: DTS2016080404468
		CVE-2016-4470	resolved	Refer: DTS2016080404468
		CVE-2016-4998	resolved	Refer: DTS2016080404468