



## E3272s-153TCPU-V200R002B436D11SP01C1209 Version Configuration Information Form



<b>Filled by</b>	<b>Chen tian tian</b>	<b>Date</b>	<b>2013-11-6</b>
------------------	-----------------------	-------------	------------------

### 1. Version Configuration Information Form of Software

<b>Area/site restriction</b>	Ghana Surflin	
<b>Other restriction</b>	None	
<b>Father's BOM</b>	51070GDV	
<b>Software Type</b>	<b>Firmware</b>	<b>Host Software</b>
<b>BOM</b>	05011YXT 终端软件 -E3272s-153-CLE3272s153020-单 板软件-程序-加纳 Surflin 1.0	05011YXV 终端软件 -HiLink-CLHOST464-后台软件-用户 程序-加纳 Surflin(WEBUI-13.100.04.01.1209)
<b>Version</b>	<a href="#">V200R002B436D11SP01C1209</a>	<a href="#">WEBUI-13.100.04.01.1209</a>
<b>Software Name</b>	<a href="#">CLE3272s153020V200R002B436 D11SP01C1209</a>	
<b>Load Notes</b>	E3272Update_22.436.11.01.1209.bin E3272Update_22.436.11.01.1209.exe	
<b>Operation Platform</b>		<b>Windows</b> <b>MAC OS</b>
<b>Location of Carrier</b>	<b>None</b>	<b>None</b>
<b>Notes</b>		