



## E3272s-153TCPU-V200R001B436D05SP01C84 Version Configuration Information Form



Filled by	Houhongyan	Date	2013-10-18
-----------	------------	------	------------

### 1. Version Configuration Information Form of Software

Area/site restriction	<b>Portugal PT-TMN</b>	
Other restriction	None	
Father's BOM	<b>51070EDX</b>	
Software Type	<b>Firmware</b>	<b>Host Software</b>
BOM	05011VHL	05011VHN
Version	21.436.05.01.84	UTPS23.009.17.01.84_MA C23.009.17.01.84
Software Name	CLE3272s153003V200R001B436D05SP01 C84	
Load Notes	E3272UPDATE_21.436.05.01.84.BIN E3272Update_21.436.05.01.84.exe	
Operation Platform		<b>Windows</b> <b>MAC OS</b>
Location of Carrier	<b>None</b>	<b>None</b>
Notes		