



## E3531s-2TCPU-V200R001B318D15SP00C208Version Configuration Information Form



Filled by	81004730	Date	2013-10-29
-----------	----------	------	------------

### 1. Version Configuration Information Form of Software

Area/site restriction	Serbia Telenor	
Other restriction	None	
Father's BOM	51070GGM	
Software Type	Firmware	Dashboard
BOM	05011YJW 终端软件-E3531s-2-CHE3531s2005-单板软件-程序-塞尔维亚 Telenor 1.0	05011YJY 终端软件 -E3531s-2-CPHOST66 1-后台软件-用户程序-塞尔维亚 Telenor 定制 -含手册
Version	21.318.15.00.208	UTPS23.012.05.00.20 8_MAC23.012.05.00.2 08
Software Name	CHE3531s2005V200R001B318D15SP00C208	
Load Notes	E3531_UPDATE_21.318.15.00.208.exe E3531_UPDATE_21.318.15.00.208.BIN	
Operation Platform		WINDOWS/MAC OS
Location of Carrier	None	None
Notes		